



June 16, 2016

To Whom It May Concern:

Recently, TEK Environmental reported that lead was detected at GEE White and Edmonson in a couple drinking fountains. The following is the procedure GEE and TEK Environmental will follow to resolve the issue at hand.

1. Identify the drinking fountains. Already has been complete.
2. Eliminate the usage of that drinking fountain. Have already removed them from usage.
3. Change faucets of the affected drinking fountain.
4. Retest.
5. Send report to board and city.

If you have any questions, please contact Rushdi Issa at 734-717-3833

Thank you,

Rushdi Issa