
OW2201 - Pla No Accent Plates







A B SOURCE (Select one) and VOLTAGE D COPTICAL DISTRIBUTION (Select one)

MVOLT fixture accepts 120 through 277 input voltage White LED Sources are dimmable 0-10V to 10% (not available with pencil beam optic)

White LED Sources are 93CRI, within 3-step MacAdam

White Pencil Beam Sources are 82CRI within 3-step MacAdam

B Source Voltage Doptic CCT per direction (up/down)

Delivered Lumens
MED NRW Power (Watts)

 L35K
 MVOLT
 MED (50° Beam) NRW (23° Beam)
 3000K 3500K 4000K
 2200
 1600
 29


				P	
AMB				670	
BLU				230	
GRN		D (D)		530	
RED	MVOLT	T P (Pencil Beam) Not dimmable		400	12
L30K		1 Noi diffilliable	3000K	730	
L35K			3500K	750	
L40K			4000K	790	

NONE If an uplight or downlight source is not needed, choose none

From the welcoming glow for the entry to the functional façade lighting, in a durable, attractive wall mounted fixture yielding both dramatic accent lighting and functional area lighting without sacrificing efficiency

DIMENSIONS Depth is measured from wall to front of fixture W = Width H = Height D = Depth

W 7" (178 mm) H 18" (457 mm) D 10-1/8" (257 mm)



FINISHES (Select one)

Powder Coat Painted Finishes (Standard)

AG7038	Agate Grey	CVBL	Cove Blue	GW9002	Grey White	PB1035	Pearl Beige
BMAT	Bronze Matte	CW9001	Cream	HTHR	Heather	RUST	Rust
BRNZ	Bronze	GLIM	Glimmer	JB9005	Jet Black	SUNG	Sungold
BSIL	Blade Silver	GSIL	Graphite Silver	OBRZ	Old Bronze	TW9016	Traffic White

ACCESSORIES - Order Separately

Remote emergency line voltage inverter - Surface or cabinet mount

PS-EMVL Can supply a single fixture up to 20W at 120V or 277V for 90 minutes

PS-EMVM Can supply multiple fixtures up to a combined 125W at 120V or 277V for 90 minutes **PS-EMVH** Can supply multiple fixtures up to a combined 375W at 120V or 277V for 90 minutes







See page 2 for color chart

LED


FTL Listed


5 Year Warranty

OW2201 - Plā **No Accent Plates**



Photometrics (per direction - up/down)






Technical Information


- Integral high power factor electronic power supply with MVOLT operation in wall bracket canopy
- Modular design for replacement of LED source and power supply
- IP65 rated
- Bracket mounting system simplifies installation and maintenance
- Mounts over 4" junction box
- Tamper resistant fasteners
- Meets seismic guidelines for weight
- Cast and fabricated aluminum
- No VOC powder coat paint finish

Relative Scale Drawing




Path of Egress

L35K, 50 degree beam spread, downlight only, mounted 16' above grade, .70 light loss factor used



Specify color code when ordering. For accurate color matching, individual paint and finish samples are available upon request For additional information see VisaLighting.com/materials-finishes

Painted Finishes (Standard)



This document contains information which is the property of Visa Lighting, and may not, in whole or in part, be duplicated, disclosed, or used for design or manufacturing purposes without the prior written permission of Visa Lighting. @Visa Lighting. Design Modification Rights Reserved.



Finish color - Pebble Grey (RAL7032)

11 5/8" 3 1/4" 14 1/8"

Weight: 1.5 lbs

Project: ___ Fixture Type: _ Quantity:

Customer:





A polyester powder coat high quality finish is electro-statically applied and baked at 430° for exceptional durability and color retention. Products undergo an intensive five-step cleansing and pretreatment process for maximum paint adhesion.

Marine grade finish provides superior salt. humidity and UV protection. This coating withstands up to 3000 hours of continuous salt spray, comes with a 5-year warranty and is available in either a textured or gloss surface.

Consult factory for custom or modified luminaires.

Material:

RLM shades are constructed of heavy duty spun aluminum. Wall back plate and driver housing are cast aluminum. All fasteners are stainless steel. Inside of shade is reflective white finish for all colors except galvanized paint finish. Screw hardware may not match

Specifications

Electrical: GU24 socket, 120V only. Universal voltage 120-277 is standard. 0-10V, TRIAC and ELV dimming protocols are standard for LED modules. (12w is TRIAC dimming & 120v only)


See page 2 table for LED module and driver specs, voltage and dimming protocols

Certifications:

Cord mounts are UL Listed for dry locations. Arm mount, stem mount and wall mount are UL Listed for wet locations.

A814 **LED**

> 30K 35K







D (Dimming) See page 2 table for LED engine and driver specs, voltage and dimming protocols.

DISTRIBUTION W (T5 Wide Distribution with Dome LED Lens) N* (T5 Narrow Distribution with Flat LED Lens) *12w is narrow only, select "N" 4 **COLOR TEMPERATURE (CCT)**

40K (4000K) (Not Sunset Dim) 5 **DRIVER HOUSING** RTC (Driver Canopy) RTCNC (Driver Canopy/No Spun Cover) NA

(3500K) (Not Sunset Dim)

6	VOLTAGE
UNV (120-277)	

′		IVIOU	1411140	SOUNC	LO
	Arm M	ounts (0	Cast back	plate in	cluded (CB))
E3 E4	E6 E7	E8			
E10 E1	1 E12	E18 E2	.5		
(See St	ep 5 for	Driver	Housing	Options)	
			Wall Mo	ounts	
WM54					
WM317					
			Stem Mo	ounts	
1/2" (13	/16" OD	Rigid S	stems wit	h STC FI	at Canopy)
2ST6	2ST12	2ST18	2ST24	2ST36	2ST48
2ST60	2ST72	2ST96			
3/4" (1"	OD Rig	id Stem	s with ST	C Flat C	anopy)
3ST6 3	ST12	3ST18	3ST24	3ST36	3ST48
3ST60	3ST72	3ST9	6		
(See St	ep 5 for	Driver	Housing	Options)	

MOUNTING SOURCES

8	ACCESSORIES
СВС	(Cast back plate Spun Alum Cover)
GR14	(14" Wire Grill)
PC	(Button Photo Cell) Remote Only
sc	(Scroll for Arms)
SLC	(Sloped Ceiling Mount, 20° Max)
SQ	(Square Back Plate)
SWL	(Swivel)
твк	(Turn Buckle Kit)

9		FINIS	SHES		
Standard Grade	Marine Grade	_	Standard Grade	Marine Grade	
40	NA	Raw Unfinished	53	100	Copper Clay
41	101	Black	56	109	Silver
42	102	Forest Green	61	106	Black Verde
43	114	Bright Red	70	118	Painted Chrome
44	107	White	71	105	Painted Copper
45	112	Bright Blue	72	108	Textured Black
46	123	Sunny Yellow	73	125	Matte Black
47	120	Aqua Green	76	121	Textured Architectural Bronze
49	NA	Galvanized	77	127	Textured White
50	111	Navy	78	124	Textured Silver
51	103	Architectural Bronze	10	130	Aspen Green
52	104	Patina Verde	11	131	Cantaloupe
12	133	Lilac	13	132	Putty
Premium Grade	Marine Grade		Premium Grade	Marine Grade	
81	129	Extreme Chrome	64	116	Candy Apple Red
80	117	Textured Desert Stone	65	122	Cobalt Blue
67	119	Butterscotch	82	128	Graystone
66	115	Caramel	69	113	Gunmetal Gray
68	126	Black Silver	83	134	Oil Rubbed Bronze

Consult factory for additional paint charges and availability

Specifications A814-M016LD-D-W-40K-RTC-E6

Project:	
Fixture Type:	Quantity:
Customer:	

LED PERFORMANCE

	MODULE								
LED Wattage	ССТ	Typical Luminous Flux	System Wattage	Typical Efficacy					
	2700K	850	11W	97					
9W	3000K	850	11W	97					
344	3500K	850	11W	97					
	4000K	850	11W	97					
	2700K	1250	12W	125					
10W	3000K	1250	12W	125					
1000	3500K	1250	12W	125					
	4000K	1250	12W	125					
	2700K	750	12W	65					
12W	3000K	750	12W	65					
1200	3500K	750	12W	65					
	4000K	750	12W	65					
	2700K	2000	19W	125					
16W	3000K	2000	19W	125					
1000	3500K	2000	19W	125					
	4000K	2000	19W	125					

MODULE SPECIFICATION

- Efficacy 65-125 lumens per watt
- Dimmable down to 1%
- Life: L70 50,000 hours
- Color temp: 2700K,3000K,3500K and 4000K
- CRI: >90

MODULE DRIVER SPECIFICATION

- Input Voltage: 120-277 Volts; 50/60Hz
- 0-10V, TRIAC and ELV dimming protocols are standard. (24w is 0-10v only)
- Output Current: Constant Current: 440mA to 940mA (model dependent)
- Driver Efficiency > 80%; Power Factor > 0.9
- Integral Surge Protection in conformance to ANSI C62.41 Category A

MODULE LISTINGS

- Fully compliant with the RoHS Directive
- Certifications: CE/UL

WARRANTY


See www.anplighting.com for complete fixture warranty.

LED warranty information

• 5 year limited warranty*

*Limited Warranty: A typical year is defined as 4380 hours of operation.

Project:	
Fixture Type:	Quantity:
Customer:	













RSX1 LED Area Luminaire











Hit the Tab key or mouse over the page to see all interactive elements

Specifications


EPA (ft²@0°): 0.57 ft² (0.05 m²)

Length: 21.8" (55.4 cm) (SPA mount)

Width: 13.3" (33.8 cm)

Height: 3.0" (7.6 cm) Main Body 7.2" (18.4 cm) Arm

Weight (max): 31.0 lbs (14.1 kg)





Introduction

The new RSX LED Area family delivers maximum value by providing significant energy savings, long life and outstanding photometric performance at an affordable price. The RSX1 delivers 7,000 to 17,000 lumens allowing it to replace 70W to 400W HID luminaires.

The RSX features an integral universal mounting mechanism that allows the luminaire to be mounted on most existing drill hole patterns. This "no-drill" solution provides significant labor savings. An easy-access door on the bottom of mounting arm allows for wiring without opening the electrical compartment. A mast arm adaptor, adjustable integral slipfitter and other mounting configurations are available.

Ordering Information

EXAMPLE: RSX1 LED P4 40K R3 MVOLT SPA DDBXD

RSX1 LED					
Series	Performance Package	Color Temperature	Distribution	Voltage	Mounting
RSX1 LED	P1 P2 P3 P4	30K 3000K 40K 4000K 50K 5000K	R2 Type 2 Wide R3 Type 3 Wide R3S Type 3 Short R4 Type 4 Wide R4S Type 4 Short R5 Type 5 Wide R5S Type 5 Short AFR Automotive Front R0 AFRR90 Automotive Front R0 Right Rotated AFRL90 Automotive Front R0 Left Rotated		SPA Square pole mounting (3.0" min. SQ pole for 1 at 90°, 3.5" min. SQ pole for 2, 3, 4 at 90°) RPA Round pole mounting (3.2" min. dia. RND pole for 2, 3, 4 at 90°, 3.0" min. dia. RND pole for 1 at 90°, 2 at 180°, 3 at 120°) MA Mast arm adaptor (fits 2-3/8" OD horizontal tenon) IS Adjustable slipfitter (fits 2-3/8" OD tenon) 4 WBA Wall bracket WBASC Wall bracket with surface conduit box AASP Adjustable tilt arm square pole mounting 4 AARP Adjustable tilt arm round pole mounting 4 AAWB Adjustable tilt arm with wall bracket 4 AAWSC Adjustable tilt arm wall bracket and surface conduit box 4

Options			Finish	
Shipped Ir HS PE PEX PER7 CE34 SF DF SPD20KV FAO DMG	House-side shield ⁵ Photocontrol, button style ^{6,7} Photocontrol external threaded, adjustable ^{7,8} Seven-wire twist-lock receptacle only (no controls) ^{7,9,10,11} Conduit entry 3/4" NPT (Qty 2) Single fuse (120, 277, 347) ³ Double fuse (208, 240, 480) ³ 20KV Surge pack (10KV standard) ^{7,11} Field adjustable output ^{7,11} 0-10V lead wires extended (no controls) ^{7,11}	*Standalone and Networked Sensors/Controls (factory default settings, see table page 9) NLTAIR2	DDBXD DBLXD DNAXD DWHXD DDBTXD DBLBXD DNATXD DWHGXD	Dark Bronze Black Natural Aluminum White Textured Dark Bronze Textured Black Textured Natural Aluminum Textured White



Ordering Information

Accessories

RSX1HS RSX1 House side shield (includes 1 shield)

RSX1HSAFRR U RSX1 House side shield for AFR rotated optics (includes 1 shield)

RSX1EGS (FINISH) U External glares hield (specify finish) RSX1EGFV (FINISH) U External glare full visor (specify finish)

RSXRPA (FINISH) U RSX Universal round pole adaptor plate (specify finish)

RSXWBA (FINISH) U RSX WBA wall bracket (specify finish)

RSXSCB (FINISH) U RSX Surface conduit box (specify finish, for use with WBA, WBA not included) Photocell -SSL twist-lock (120-277V) 16 DLL127F 1.5 JU DLL347F 1.5 CUL JU Photocell -SSL twist-lock (347V) 16

DLL480F 1.5 CUL JU Photocell -SSL twist-lock (480V) 16 DSHORT SBK U Shorting cap 1

- TES

 MVOLT driver operates on any line voltage from 120-277V (50/60 Hz).

 HVOLT driver operates on any line voltage from 347-480V (50/60 Hz).

 Single fuse (SF) requires 120V, 277V or 347V. Double fuse (DF) requires 208V, 240V or 480V.

 Maximum tilt is 90° above horizontal. It may be ordered as an accessory.

 Requires MVOLT or 347V.

- Not available in combination with other light sensing control options (following options cannot be combined: PE, PEX, PER7, FAO, DMG, PIRHN).
- Requires 120V, 208V, 240V, 277V or 347V.
- Twistlock photocell ordered and shipped as a separate line item from Acuity Brands Controls. See accessories. Shorting Cap included. Dimming leads capped for future use.
- For units with option PER7, the mounting must be restricted to +/- 45° from horizontal aim per ANSI C136.10-2010. Two or more of the following options cannot be combined including DMG, PER7, FAO and PIRHN.

- Must be ordered with PIRHN.
 Requires MVOLT or HVOLT.
 Must be ordered with NLTAIR2. For additional information on PIRHN
- wish there.

 Must be ordered with fixture for factory pre-drilling.

 Requires luminaire to be specified with PER7 option. Ordered and shipped as a separate line item from Acuity Brands Controls.

External Shields



House Side Shield



External Glare Shield




External 360 Full Visor


Pole/Mounting Informatiion

Accessories including bullhorns, cross arms and other adpaters are available under the accessories tab at Lithonia's Outdoor Poles and Arms product page. Click here to visit Accessories.


HANDHOLE ORIENTATION



RSX POLE DRILLING



RSX STANDARD ARM & ADJUSTABLE ARM



Round Tenon Mount - Pole Top Slipfitters

Tenon O.D.	RSX Mounting	Single	2 at 180°	2 at 90°	3 at 120°	3 at 90°	4 at 90°
2 - 3/8"	RPA, AARP	AS3-5 190	AS3-5 280	AS3-5 290	AS3-5 320	AS3-5 390	AS3-5 490
2 - 7/8"	RPA, AARP	AST25-190	AST25-280	AST25-290	AST25-320	AST25-390	AST25-490
4"	RPA, AARP	AST35-190	AST35-280	AST35-290	AST35-320	AST35-390	AST35-490

Drill/Side Location by Configuration Type

		-		-	**		-1-
Drilling Template	Mounting Option	Single	2 @ 180	2 @ 90	3 @ 120	3 @ 90	4 @ 90
	Head Location	Side B	Side B & D	Side B & C	Round Pole Only	Side B, C & D	Side A, B, C & D
#8	Drill Nomenclature	DM19AS	DM28AS	DM29AS	DM32AS	DM39AS	DM49AS

RSX1 - Luminaire EPA


*Includes luminaire and integral mounting arm. Other tenons, arms, brackets or other accessories are not included in this EPA data.


Fixture Quantity & Mounting Configuration		Single	2 @ 90	2 @ 180	3 @ 90	3 @ 120	4 @ 90	2 Side by Side	3 Side by Side	4 Side by Side
Mounting Type	Tilt	-	-1		<u>.</u>	*	+	•		m
SPA - Square Pole Adaptor		0.57	1.03	1.05	1.52	1.36	2.03	1.31	1.7	2.26
RPA - Round Pole Adaptor	0°	0.62	1.08	1.15	1.62	1.46	2.13	1.36	1.8	2.36
MA - Mast Arm Adaptor		0.49	0.95	0.89	1.36	1.2	1.87	1.23	1.54	2.1
	0°	0.57	1.03	1.05	1.52	1.36	2.03	1.31	1.7	2.26
	10°	0.68	1.34	1.33	2	1.74	2.64	1.35	2.03	2.71
	20°	0.87	1.71	1.73	2.56	2.26	3.42	1.75	2.62	3.49
	30°	1.24	2.19	2.3	3.21	2.87	4.36	2.49	3.73	4.97
IS - Integral Slipfitter	40°	1.81	2.68	2.98	3.85	3.68	5.30	3.62	5.43	7.24
AASP/AARP - Adjustable	45°	2.11	2.92	3.44	4.2	4.08	5.77	4.22	6.33	8.44
Arm Square/Round Pole	50°	2.31	3.17	3.72	4.52	4.44	6.26	4.62	6.94	9.25
	60°	2.71	3.66	4.38	5.21	5.15	7.24	5.43	8.14	10.86
	70°	2.78	3.98	4.54	5.67	5.47	7.91	5.52	8.27	11.03
	80°	2.76	4.18	4.62	5.97	5.76	8.31	5.51	8.27	11.03
	90°	2.73	4.25	4.64	6.11	5.91	8.47	5.45	8.18	10.97


Photometric Diagrams


To see complete photometric reports or download .ies files for this product, visit Lithonia Lighting's RSX Area homepage.


Isofootcandle plots for the RSX1 LED P4 40K. Distances are in units of mounting height (20').

















Performance Data

Lumen Ambient Temperature (LAT) Multipliers

Use these factors to determine relative lumen output for average ambient temperatures from 0-50°C (32-122°F).

Ambient	Ambient	Lumen Multiplier
0°C	32°F	1.05
5°C	41°F	1.04
10°C	50°F	1.03
15℃	59°F	1.02
20°C	68°F	1.01
25°C	77°F	1.00
30°C	86°F	0.99
35°C	95°F	0.98
40°C	104°F	0.97
45°C	113°F	0.96
50°C	122°F	0.95

Electrical Load

					nt (A)		
Performance Package	System Watts (W)	120V	208V	240V	277V	347V	480V
P1	51W	0.42	0.25	0.21	0.19	0.14	0.11
P2	72W	0.60	0.35	0.30	0.26	0.21	0.15
P3	109W	0.91	0.52	0.45	0.39	0.31	0.23
P4	133W	1.11	0.64	0.55	0.48	0.38	0.27

Projected LED Lumen Maintenance

Operating Hours	50,000	75,000	100,000
Lumen Maintenance Factor	>0.97	>0.95	>0.92

Values calculated according to IESNA TM-21-11 methodology and valid up to 40° C.

Performance Data

Lumen Output


Lumen values are from photometric tests performed in accordance with IESNA LM-79-08. Data is considered to be representative of the configurations shown, within the tolerances allowed by Lighting Facts. Contact factory for performance data on any configurations not shown here.

Performance	System Watts	Distribution.			30K K, 70 CR	I)				40K K, 70 CR	I)				50K K, 70 CR	I)	
Package		Туре	Lumens	В	U	G	LPW	Lumens	В	U	G	LPW	Lumens	В	U	G	LPW
		R2	6,482	1	0	1	126	7,121	1	0	1	139	7,121	1	0	1	139
		R3	6,459	1	0	2	127	7,096	1	0	2	139	7,096	1	0	2	139
		R3S	6,631	1	0	1	129	7,286	1	0	2	142	7,286	1	0	2	142
		R4	6,543	1	0	2	128	7,189	1	0	2	141	7,189	1	0	2	141
P1	51W	R4S	6,313	1	0	1	124	6,936	1	0	1	136	6,936	1	0	1	136
l ri	J JIW	R5	6,631	3	0	2	130	7,286	3	0	2	143	7,286	3	0	2	143
		R5S	6,807	3	0	1	133	7,479	3	0	1	147	7,479	3	0	1	147
		AFR	6,473	1	0	1	127	7,112	1	0	1	139	7,112	1	0	1	139
		AFRR90	6,535	2	0	2	127	7,179	2	0	2	140	7,179	2	0	2	140
		AFRL90	6,562	2	0	1	128	7,210	2	0	2	140	7,210	2	0	2	140
		R2	8,991	2	0	1	123	9,878	2	0	1	135	9,878	2	0	1	135
		R3	8,959	2	0	2	124	9,843	2	0	2	137	9,843	2	0	2	137
		R3S	9,198	2	0	2	126	10,106	2	0	2	139	10,106	2	0	2	139
		R4	9,077	2	0	2	126	9,972	2	0	2	139	9,972	2	0	2	139
P2	72W	R4S	8,757	1	0	2	122	9,622	2	0	2	134	9,622	2	0	2	134
	/200	R5	9,198	4	0	2	128	10,106	4	0	2	140	10,106	4	0	2	140
		R5S	9,443	3	0	1	131	10,374	3	0	1	144	10,374	3	0	1	144
		AFR	8,979	2	0	1	125	9,865	2	0	1	137	9,865	2	0	1	137
		AFRR90	9,064	3	0	2	124	9,959	3	0	2	137	9,959	3	0	2	137
		AFRL90	9,102	3	0	2	125	10,001	3	0	2	137	10,001	3	0	2	137
		R2	12,808	2	0	1	117	14,072	2	0	2	129	14,072	2	0	2	129
		R3	12,763	2	0	2	117	14,023	2	0	2	129	14,023	2	0	2	129
		R3S	13,104	2	0	2	120	14,397	2	0	2	132	14,397	2	0	2	132
		R4	12,930	2	0	2	119	14,206	2	0	2	130	14,206	2	0	2	130
P3	109W	R4S	12,475	2	0	2	114	13,707	2	0	2	126	13,707	2	0	2	126
"	10344	R5	13,104	4	0	2	120	14,397	4	0	2	132	14,397	4	0	2	132
		R5S	13,452	3	0	2	123	14,779	3	0	2	136	14,779	3	0	2	136
		AFR	12,791	2	0	1	117	14,053	2	0	2	129	14,053	2	0	2	129
		AFRR90	12,913	3	0	3	118	14,187	3	0	3	130	14,187	3	0	3	130
		AFRL90	12,967	3	0	2	118	14,247	3	0	3	130	14,247	3	0	3	130
		R2	14,943	2	0	2	112	16,417	2	0	2	123	16,417	2	0	2	123
		R3	14,890	2	0	3	112	16,360	2	0	3	123	16,360	2	0	3	123
		R3S	15,287	2	0	2	115	16,796	2	0	2	126	16,796	2	0	2	126
		R4	15,085	2	0	3	113	16,574	2	0	3	125	16,574	2	0	3	125
P4	133W	R4S	14,554	2	0	2	109	15,991	2	0	2	120	15,991	2	0	2	120
r4	133W	R5	15,287	4	0	2	115	16,796	4	0	2	126	16,796	4	0	2	126
		R5S	15,693	4	0	2	118	17,242	4	0	2	130	17,242	4	0	2	130
		AFR	14,923	2	0	2	112	16,395	2	0	2	123	16,395	2	0	2	123
		AFRR90	15,065	3	0	3	113	16,551	3	0	3	124	16,551	3	0	3	124
		AFRL90	15,128	3	0	3	114	16,621	3	0	3	125	16,621	3	0	3	125




Dimensions

RSX1 with Round Pole Adapter (RPA)




Length: 22.8" (57.9 cm) Width: 13.3" (33.8 cm)

Height: 3.0" (7.6 cm) Main Body 7.2" (18.4 cm) Arm




RSX1 with Mast Arm Adapter (MA)




Length: 23.2" (59.1 cm) Width: 13.3" (33.8 cm)

Height: 3.0" (7.6 cm) Main Body 3.5" (8.9 cm) Arm







RSX1 with Adjustable Slipfitter (IS)




Length: 20.7" (52.7 cm) Width: 13.3" (33.8 cm)


Height: 3.0" (7.6 cm) Main Body 7.6" (19.3 cm) Arm






RSX1 with Wall Bracket (WBA)










Wall Bracket (WBA) Mounting Detail

Length: 23.6" (59.9 cm) Width: 13.3" (33.8 cm)


Height: 3.0" (7.6 cm) Main Body 8.9" (22.6 cm) Arm










RSX1 with Wall Bracket with Surface Conduit Box (WBASC)









Surface Conduit Box (SCB) Mounting Detail










Length: 25.3" (64.3 cm) Width: 13.3" (33.8 cm) Height: 3.0" (7.6 cm) Main Body

9.2" (23.4 cm) Arm


RSX1 with Adjustable Tilt Arm - Square or Round Pole (AASP or AARP)







Length: 25.3" (65.3 cm) AASP 26.3" (66.8 cm) AARP Width: 13.3" (33.8 cm) Height: 3.0" (7.6 cm) Main Body 7.2" (18.2 cm) Arm





Notes


AASP: Requires 3.0" min. square pole for 1 at 90°. Requires 3.5" min. square pole for mounting 2, 3, 4 at 90°.


AARP: Requires 3.2" min. dia. round pole for 2, 3, 4 at 90°. Requires 3.0" min. dia. round pole for mounting 1 at 90°, 2 at 180°, 3 at 120°.

RSX1 with Adjustable Tilt Arm with Wall Bracket (AAWB)





















Length: 27.1" (68.8 cm) Width: 13.3" (33.8 cm) Height: 3.0" (7.6 cm) Main Body

8.9" (22.6 cm) Arm




Dimensions


RSX1 with Adjustable Tilt Arm with Wall Bracket and Surface Conduit Box (AAWSC)



Additional Reference Drawings




Automotive Front Row - Rotated Optics (AFRL90/R90)




nLight Control - Sensor Coverage and Settings

PIRHN nLight Sensor Coverage Pattern







Motion Sensor Default Settings - Option PIRHN									
Option	Dimmed State (unoccupied)	High Level (when occupied)	Photocell Operation	Dwell Time (occupancy time delay)	Ramp-up Time (from unoccupied to occupied)	Ramp-down Time (from occupied to unoccupied)			
PIRHN	Approx. 30% Output	100% Output	Enabled @ 1.5FC	7.5 minutes	3 seconds	5 minutes			

^{*}Note: PIRHN default settings including photocell set-point, high/low dim rates, and occupancy sensor time delay are all configurable using the Clairity Pro App.

FEATURES & SPECIFICATIONS

INTENDED USE

The RSX LED area family is designed to provide a long-lasting, energy-efficient solution for the onefor-one replacement of existing metal halide or high pressure sodium lighting. The RSX1 delivers 7,000 to 17,000 lumens and is ideal for replacing 70W to 400W HID pole-mounted luminaires in parking lots and other area lighting applications.

CONSTRUCTION

The RSX LED area luminaire features a rugged die-cast aluminum main body that uses heat-dissipating fins and flow-through venting to provide optimal thermal management that both enhances LED performance and extends component life. Integral "no drill" mounting arm allows the luminaire to be mounted on existing pole drillings, greatly reducing installation labor. The light engines and housing are sealed against moisture and environmental contaminants to IP66. The low-profile design results in a low EPA, allowing pole optimization. All mountings are rated for a 1.5 G vibration load per ANSI C136.31. WITH Vibration rated per ANSI C136.31: 3G Mountings: SPA, RPA, MA, IS, AASP, and AARP rated for 3G vibration. 1.5G Mountings: WBA, WBASC, AAWB and AAWSC rated for 1.5G vibration.

FINISH

Exterior parts are protected by a zinc-infused Super Durable TGIC thermoset powder coat finish that provides superior resistance to corrosion and weathering. A tightly controlled multi-stage process ensures superior adhesion as well as a minimum finish thickness of 3 mils. The result is a high-quality finish that is warrantied not to crack or peel.

OPTICS

Precision acrylic refractive lenses are engineered for superior application efficiency, distributing the light to where it is needed most. Available in short and wide pattern distributions including Type 2, Type 3, Type 35, Type 4, Type 45, Type 5, Type 5S, AFR (Automotive Front Row), and AFR rotated AFRR90 and ARFL90.

ELECTRICAL

Light engine(s) configurations consist of high-efficacy LEDs mounted on metal-core circuit boards and aluminum heat sinks to maximize heat dissipation. Light engines are IP66 rated. LED lumen maintenance is >192/100,000 hours. CCT's of 3000K, 4000K and 5000K (minimum 70 CRI) are available. Class 1 electronic drivers ensure system power factor >90% and THD <20%. Easily serviceable 10kV surge protection device meets a minimum Category C Low operation (per ANSI/ IEEE C62.41.2).

STANDARD CONTROLS

The RSX LED area luminaire has a wide assortment of control options. Dusk to dawn controls include MVOLT and 347V button-type photocells and NEMA twist-lock photocell receptacles.

nLIGHT AIR CONTROLS

The RSX LED area luminaire is also available with nLight® AIR for the ultimate in wireless control. This powerful controls platform provides out-of-the-box basic motion sensing with photocontrol functionality and is suitable for mounting heights up to 40 feet. No commissioning is required when using factory default settings that provide basic stand-alone motion occupancy dimming that is switched on and off with a built-in photocell. See chart above for motion sensor default out-of-box settings. For more advanced wireless functionality, such as group dimming, nLight AIR can be commissioned using a smartphone and the easy-to-use CLAIRITY app. nLight AIR equipped luminaries can be grouped, resulting in motion sensor and photocell group response without the need for additional equipment. Scheduled dimming with motion sensor over-ride can be achieved when used with the nLight Eclypse. Additional information about nLight Air can be found here.

INSTALLATION

Integral "no-drill" mounting arm allows for fast, easy mounting using existing pole drillings. Select the "SPA" option for square poles and the "RPA" option to mount to round poles. Note, the RPA mount can also be used for mounting to square poles by omitting the RPA adapter plate. Select the "MA" option to attach the luminaire to a 2 3/8" horizontal mast arm or the "IS" option for an adjustable slipfitter that mounts on a 2 3/8" OD tenon. The adjustable slipfitter has an integral junction box and offers easy installation. Can be tilted up to 90° above horizontal. Additional mountings are available including a wall bracket, adjustable tilt arm for direct-to-pole and wall and a surface conduit box for wall mount applications.

LISTINGS

CSA Certified to meet U.S. and Canadian standards. Suitable for wet locations. Rated for -40°C minimum ambient. DesignLights Consortium® (DLC) Premium qualified product and DLC qualified product. Not all versions of this product may be DLC Premium qualified or DLC qualified. Please check the DLC Qualified Products List at www.designlights.org/QPL to confirm which versions are qualified.

WARRANTY

5-year limited warranty. Complete warranty terms located at: www.acuitybrands.com/resources/terms-and-conditions

Note: Actual performance may differ as a result of end-user environment and application. All values are design or typical values, measured under laboratory conditions at 25 °C. Specifications subject to change without notice.





A New Standard for Building Mount Solutions!

Whether you are trying to meet specification, code, or seeking a building mount solution with the right options, the WST LED is your go-to solution delivering a visually comfortable lighting experience. The WST LED offers the optics and lumens you need, combined with a comprehensive variety of battery backup, controls, and other options to meet your specification or building code.

Optics with Visual Comfort

- Two optic types; a wide distribution and forward throw with three lumen packages ranging from 1,500 to 6,600 lumens
- Superior luminaire design delivers visually comfortable lighting by providing low glare without pixilation
- Excellent uniformity allows for increased spacing, substantially lowering the overall cost of your project

Comprehensive Options: Battery, Controls, and More

- Industry-leading, comprehensive selection of emergency battery backup solutions for every application type and climate, including remote emergency options
- The widest variety of control options providing site-wide monitoring and control increases your energy savings even further
- Dual switching and a complete selection of battery and controls options aid in ensuring code compliance

DLC Qualified

DesignLights Consortium® Premium qualified, which makes the WST LED eligible for utility rebates and can help improve project ROI.





Quick Facts

- Replaces 50W 250W metal halide wallpacks
- Lumen packages from 1,500 - 6,600 lumens
- Up to 140 LPW
- Input watts from 12W 58W
- Two optic types: wide distribution and forward throw
- 2700K CCT, 3000K CCT, 4000K CCT, and 5000K CCT
- Weight: 20 lbs.

WST LED

WST LED

Ordering Information

Example: WST LED P2 40K VW MVOLT PBBW PIR DDBTXD


Series	Performance Package	Color temperature	Distribution	Voltage	Mounting	Options		Finish (requ	uired)
WST LED	P1 1,500 Lumen package P2 3,000 Lumen package P3 6,000 Lumen package	27K 2700 K 30K 3000 K 40K 4000 K 50K 5000 K	VF Visual comfort forward throw VW Visual comfort wide	MVOLT 120 208 240 277 347 480	Shipped included (blank) Surface mounting bracket Shipped separately BBW Surface- mounted back box PBBW Premium surface- mounted back box LCE Left side conduit entry RCE Right side conduit entry	PE PER PERS PER7 PIR PIR1FC3V PIRH PIRH1FC3V SF DF DS E7WH E7WC E7WHR E20WH	Photoelectric cell, button type NEMA twist-lock receptacle only Five-wire receptacle only Seven-wire receptacle only Motion/Ambient Light Sensor, 8-15' mounting height Motion/ambient sensor, 8-15' mounting height, ambient sensor enabled at 1fc 180° motion/ambient light sensor, 15-30' mounting height Motion/ambient sensor, 15-30' mounting height, ambient sensor enabled at 1fc Single fuse (120, 277, 347V) Double fuse (208, 240, 480V) Dual switching Emergency battery backup (7W) Emergency battery backup (cold, 7W) Remote emergency battery backup (remote 7W) Emergency battery backup (20W)	DDBXD DBLXD DNAXD DWHXD DSSXD DDBTXD DBLBXD DNATXD DWHGXD DSSTXD	Dark bronze Black Natural aluminum White Sandstone Textured dark bronze Textured black Textured natural aluminum Textured white Textured sandstone

Battery Options

- Standard emergency battery backup options; low power (7W) or high power (20W)
- Cold weather emergency battery backup options for -20° to 60° operating temperature (low or high power)
- Remote emergency battery backup (standard, high power)



WST LED





*DesignLights Consortium® (DLC) Premium qualified product. Not all versions of this product may be DLC Premium qualified. Please check the DLC Qualified Products List at www.designlights.org/QPL to confirm which versions are qualified.

Controls Options

Shipped separately

E20WC

E23WHR

RBPW

VG

WG

Photoelectric cell, button type

Retrofit back plate

Vandal Guard

Wire Guard

Emergency battery backup (cold, 20W)

Remote emergency battery backup (remote 20W)

- NEMA three, five, and seven-wire twist-lock receptacle (receptacle only)
- Motion/ambient sensor, for 8-15' and 15-30' mounting height
- 180° motion/ambient light sensor,
 15-30' mounting height



NEMA Twist-Lock Receptacle

Other Options

- Premium surface-mounted back box
- Surface-mounted back box
- Retrofit back plate



Premium Back Box

Please use the spec sheet at www.acuitybrands.com when ordering to ensure component compatibility for your desired configuration.



- 200 REMOVE AND REPLACE CORRODED BRICK RELIEF ANGLE, SEE DETAIL X/SXXX.
- 203 REPLACE STONE.
- 204 CAREFULLY DETACH EXISTING METAL GUARDRAILS, CLEAN WITH GENTLEST MEANS POSSIBLE TO ACHIEVE SATISFACTORY RESULTS. INSPECT FOR DAMAGE AND REPAIR AS REQUIRED TO MAKE SECURE. RE-PAINT GUARD RAIL WITH COMPATABLE COLOR AND RE-INSTALL
- 209 REPLACE EXISTING FABRIC CANOPY AT HOTEL ENTRY. HOTEL SIGNAGE APPLIED AT FACE AND SIDES. SIDEWALK LIGHTING.
- 210 CAREFULLY DETACH EXISTING METAL FLAGPOLE CLEAN WITH GENTLEST MEANS POSSIBLE TO ACHIEVE SATISFACTORY RESULTS. INSPECT FOR DAMAGE AND REPAIR AS REQUIRED TO MAKE SECURE. RE-PAINT FLAGPOLE WITH COMPATABLE COLOR AND RE-INSTALL.
- NEW RESTAURANT ENTRANCE METAL CANOPY, BLACK. UP/DOWN LIGHTING. 212 RESTORE AND REPLACE NON-HISTORIC WALL SCONCES.
- 214 HISTORIC LOCATION OF ENTRY AND BLADE SIGN. DELAYED SUBMITTAL FOR SIGNAGE PERMIT.
- 215 REMOVE EXISTING NON-HISTORIC PLANTER BOXES PRIOR TO MASONRY RESTORATION. RESTORE ALL SURROUNDING MASONRY AND BAY WINDOWS RE-CONSTRUCT PLANTER BOXES TO MATCH EXISTING. SEE DETAIL X/AXXX. 216 NEW HOTEL BRAND PLAQUE X" X X".
- 217 NEW DOORS AND HARDWARE TO EMULATE HISTORIC PROFILE.
- PARKING FENCE SANDBLAST AND PAINT BLACK.
- 220 HOTEL PARKING DIRECTIONAL SIGNAGE AS ALLOWED BY HDC/SHPO/NPS.

EXTERIOR ELEVATION MATERIAL LEGEND

PNT-1 PAINT - 01 MTL-1 METAL - 01 PNT-2 PAINT - 02 BRK-2 BRICK - 01 PNT-3 PAINT - 03 STNE-3 STONE - 01

RESTORATION GENERAL NOTES

- A. ALL ELEVATIONS SHALL UNDERGO COMPLETE BRICK, STONE, AND TERRA COTTA CLEANING FROM PARAPET TO GRADE. SEE MASONRY CLEANING SPECIFICATION SECTIONS FOR DETAILS ON APPROVED CLEANING PROCEDURES, PRODUCTS, AND MANUFACTURERS.
- CLEAN FACADE USING GENTLEST MEANS POSSIBLE TO ACHIEVE SATISFACTORY
 RESULTS WITHOUT CHANGING THE SURFACE OF THE MASONRY PAY SPECIAL CLEAN FACADE USING GENTLEST MEANS POSSIBLE TO ACHIEVE SATISFACTORY RESULTS WITHOUT CHANGING THE SURPACE OF THE MASONRY, PAY SPECIAL ATTENTION TO AREAS OF EXCESSIVE SOURIOS, CONTRACTOR SHALL CONDUCT TEST PATCHES TO ENSURE THE BEST AND MOST ECONOMICAL MEANS OF CLEANING, SLIL MASONRY AND TERRA COTTA CLEANING, SHALL MEET THE SECRETARY OF INTERIOR STANDARDS FOR FRHABILITATION AS WELL AS ALL APPLICABLE NATIONAL PARK SERVICE TECHNICAL BRIEFS, SUBCONTRACTOR SHALL BE RESPONSIBLE FOR PROTECTINE ALL SUBPOLIMINIUS ABEAS. PROTECTING ALL SURROUNDING AREAS.
- CLEAN ALL STONE THAT IS TO REMAIN & LET WEATHER FOR TWO WEEKS REFORE ANY
- CLEAN ALL STONE THAT IS TO REMAIN B. LET WEATHER FOR TWO WEEKS BEFORE ANY REPLACEMENT OR PATCHING IS TO OCCUR REPLACEMENT STONE & PATCHED AREAS TO MATCH EXIST 'CLEANED' COLOR RESTORATION CONTRACTOR SHALL INSPECT ALL EXISTING MASONRY, INCLUDING BOTH SIDES OF PARAPET FULL HEIGHT, FOR STRUCTURAL STABILITY PRIOR TO BID. REINSPECT AFTER INITIAL CLEANING OF MASONRY.
- REPLACE/RESET LOOSE MASONRY UNITS AND TUCKPOINT DAMAGED MORTAR JOINTS AS REQUIRED. JOINTS SHALL BE RINSED WITH CLEAN WATER REMOVING DUST AND DEBRIS. IF NECESSARY, RECOMMEND FURTHER REHABILITATION TO ENSURE DEBRIS. IF NECESSARY, RECOMMEND FURTHER REHABILITATION TO ENSURE STABILITY OF EVERTIOR WALL AND PRAEPET CONSTRUCTION. SEE MASONRY RESTORATION SPECIFICATIONS FOR DETAILS ON APPROVED RESTORATION PROCEDURES, PRODUCTS, AND MANUFACTURERS. ALL MASONRY RESTORATION WORK SHALL MEET THE SECRETARY OF INTERIOR STANDARDS FOR REHABILITATION AS WELL AS ALL APPLICABLE NATIONAL PARK SERVICE TECHNICAL BRIEFS.
- INSPECT ALL TERRA COTTA UNITS FOR DAMAGE, SPALLING OR CRAZING.
- WHERE TERRA COTTA GLAZING HAS SPALLED AND THE CLAY SUBSTRATE IS IN GOOD WHERE TERMS COTTA BUTCHING HAS SPALLED AND THE CLAY SUBSTRATE IS IN GOOD CONDITION, CONT TABLE CLAY WITH APPROVED BREATHABLE SEALER TO MATCH COLOR OF EXISTING GLAZING.

 WHERE TERRA COTTA UNITS HAVE SPALLED SIGNIFICANTLY, PATCH DAMAGED AREAS
- WITH APPROVED MASONRY REPAIR MORTAR AS REQUIRED BY DEPTH OF DAMAGED AREA. COAT PATCHED AREA WITH APPROVED BREATHABLE SEALER TO MATCH COLOR OF EXISTING GLAZING.
- WHERE TERRA COTTA HAS DETERIORATED BEYOND REPAIR, REMOVE AFFECTED TERRA COTTA UNITS AND PROVIDE NEW TERRA COTTA UNITS TO MATCH EXISTING PROFILE, COLOR AND FINISH.

 SEE TERRA COTTA RESTORATION SPECIFICATIONS FOR APPROVED RESTORATION
- PROCEDURES, PRODUCTS, AND MANUFACTURERS. ALL TERRA COTTA RESTORATION WORK SHALL MEET THE SECRETARY OF INTERIOR STANDARDS FOR REHABILITATION AS WELL AS ALL APPLICABLE NATIONAL PARK SERVICE TECHNICAL BRIEFS.
- REMOVE ALL VINES FROM ENTIRE BUILDING FACADES.

 REMOVE EXISTING WINDOW AIR CONDITIONERS. PROVIDE WINDOW STOPS TO LIMIT OPENING TO LESS THAN 4".
- M. MASONRY/STONE RESTORATION CONTRACTOR ("SUBCONTRACTOR") TO PROVIDE ALL M. MASONRY/STONE RESTORATION CONTRACTOR ("SUBCONTRACTOR") TO PROVIDE ALL LABOR, MATERIAL, EQUIPMENT, SUPERVISION, PERMITS, AND ANY COSTS OR EXPENSES NECESSARY TO COMPLETE THE WORK, SUBCONTRACTOR JOB MOBILIZATION SHALL INCLUDE, BUT NOT BE LIMITED TO ANY NICCESSARY WORK STATION AND JOB TRAILER, MAST CLIMBING PLATFORMS, AERIAL LIFTS, SWING STAGES, ABRICADES AND WALK THROUGH SCAFFOLD AS NEEDED.

 N. BUILDING RESTORATION TO INCLUDE ALL TERMS, CONDITIONS, AND SPECIFICATIONS OF CONTRACTOR AND STAGES AND SPECIFICATIONS.
- OF ORIGINAL CONTRACT AND ANY ADDITIONAL WORK NECESSARY TO MEET THE SECRETARY OF THE INTERIOR STANDARDS FOR THE REHABILITATION OF HISTORIA PROPERTIES. THIS INCLUDES ALL WORK NECESSARY OVER AND ABOVE THAT SPECIFIED IN THE ARCHITECTURAL DRAWINGS AND OTHER CONSTRUCTION DOCUMENTS INCLUDING ALL NOTES, REGARDLESS OF TIME AND MATERIAL NECESSARY TO EXECUTE THIS WORK. ANY AREAS INDICATED WITHIN DRAWINGS ARE ONLY SUGGESTIVE IN NATURE. MASON TO MEET WITH ARCHITECT AND OWNER TO
- SUGGESTIVE IN NATURE. MASON TO MEET WITH ARCHITECT AND OWNER TO CONFIRM THE SCOPE OF WORK.

 O. SURFACES TO BE PRE-WET WITH CLEAN WATER. CLEANING SOLUTIONS TO NOT REMAIN ON SURFACES FOR MORE THAN 5 MINUTES FOLLOWED IMMEDIATELY BY LOW-PRESSURE FLOOD RINSE, UND IN MASONBY CLEANING SPECIFICATION. CLEANING IS TO BRING MASONRY/STONE UNIT AS CLOSE AS POSSIBLE TO ORIGINAL COLOR WITHOUT BURNING OR ABRASION.
- P. 100% OF MORTAR JOINTS TO BE VISUALLY INSPECTED. ALL MORTAR JOINTS 100% OF MORTAR JOINTS TO BE VISUALLY INSPECTED. ALL MORTAR JOINTS OF DETERIORATED IN EXCESS OF 36,8 INCH BEYOND FACE OF MASONEY/STONE UNIT, OR EVIDENCING UNSOUNDNESS OR CRACKING WHETHER STRUCTURAL OR OTHERWISE SHALL BE REMOVED TO A BEPTH OF 1/2" MINIMUM. WRITTEN APPROVAL BY OWNER SHALL BE REQUIRED PRIOR TO COMMENCEMENT OR FERME BY SATISFACTORY SUBMISSION OF MOCK-UP OF PROPOSED MORTAR JOINT.
- Q. NEW MORTAR APPLIED TO ALL OPEN JOINTS SHALL BE OF NO GREATER STRENGTH THAN ORIGINAL MORTAR OR MASONRY UNITS. MORTAR COLOR, TEXTURE, CONSISTENCY AND JOINT PROFILE WILL MATCH EXISTING AS CLOSE AS POSSIBLE.
- APPLY NEW, TWO COMPONENT URETHAND SEALANT AT ALL JOINTS WHERE DISSIMILAR MATERIALS MEET, AND ALL SKYWARD FACING JOINTS. BACKER ROD TO BE INSTALLED IN OPEN JOINT PRIOR TO SEALANT APPLICATION.
- NO ACCELERATORS OR OTHER ADMIXTURES SHALL BE USED WITHOUT PRIOR WRITTEN OWNER APPROVAL. ENCLOSURES AND HEAT SUFFICIENT TO PROTECT MORTAR FROM FREEZING PRIOR TO SET SHALL BE THE SOLE RESPONSIBILITY OF SUBCONTRACTOR.
- ANY MASONRY/STONE UNIT SHALL BE REPLACED WITH OWNER APPROVED MATERIAL WHEREIN SPALLING OR OTHER DETERIORATION ELIMINATED MORE THAN 5% OF THE MASONRY/STONE UNIT (MEASURED BY BRICK OR STONE FACE AREA.)

KraemerDesign Group

ROYAL PALM DETROIT
TAPESTRY BY HILTON
2305 PARK AVENUE
DETROIT MI 48226 GROUP LONG LAKE FIELD HILLS, MI 48304 MHS 35 W L



Project / Owner

ENT AND THE IDEAS AND DESIGNS PROPERTY OF KRAEMER DESIGN GROUP, LLC AND AR USED IN WHOLE OR IN PART FOR ANY REASON WITHOUT

DD BRAND REVIEW 10-09-19 SD OWNER REVIEW 02-20-19 OWNER REVIEW 02-06-19

Revision Date

Date

Project Number 2018069 Sheet Title

EXTERIOR ELEVATION

Sheet Number

A201



- 201 EXISTING WALL PAINT TO BE RESTORED WITH NEW TEXT "HOTEL ROYAL PALM".
 204 CAREFULLY DETACH EXISTING METAL GUARDRAILS, CLEAN WITH GENTLEST
 MEANS POSSIBLE TO ACHIEVE SATISFACTORY RESULTS. INSPECT FOR DAMAGE
 AND REPAIR AS REQUIRED TO MAKE SECURE. RE-PAINT GUARD RAIL WITH
 COMPATABLE COLOR AND RE-INSTALL
- 209 REPLACE EXISTING FABRIC CANOPY AT HOTEL ENTRY. HOTEL SIGNAGE APPLIED AT FACE AND SIDES. SIDEWALK LIGHTING.
- 211 NEW RESTAURANT ENTRANCE METAL CANOPY, BLACK, UP/DOWN LIGHTING
 212 RESTORE AND REPLACE NON-HISTORIC WALL SCONCES
- 212 RESTORE AND REPLACE NON-HISTORIC WALL SCONCES.
 214 HISTORIC LOCATION OF ENTRY AND BLADE SIGN. DELAYED SUBMITTAL FOR SIGNAGE PERMIT.
- 215 REMOVE EXISTING NON-HISTORIC PLANTER BOXES PRIOR TO MASONRY RESTORATION. RESTORE ALL SURROUNDING MASONRY AND BAY WINDOWS. RE-CONSTRUCT PLANTER BOXES TO MATCH EXISTING. SEE DETAIL X/AXXX.
- 217 NEW DOORS AND HARDWARE TO EMULATE HISTORIC PROFILE.
 219 REMOVE EXISTING SECURITY CAMERAS, CONDUITS ETC. PRIOR TO MASONRY RESTORATION.
- 221 RESTAURANT SIGNAGE, OF/CI.
- 222 PARKING FENCE SANDBLAST AND PAINT BLACK.
 223 PARKING GATE SANDBLAST AND PAINT BLACK.
- 223 PARKING GATE SANDBLAST AND PAINT BLAC
- 24 PARKING SIGNAGE. OF/CI.

RESTORATION GENERAL NOTES

PNT-3 PAINT - 03 STNE-3 STONE - 01

PNT-2

A. ALL ELEVATIONS SHALL UNDERGO COMPLETE BRICK, STONE, AND TERRA COTTA CLEANING FROM PARAPET TO GRADE. SEE MASONRY CLEANING SPECIFICATION SECTIONS FOR DETAILS ON APPROVED CLEANING PROCEDURES, PRODUCTS, AND MANUFACTURERS.

EXTERIOR ELEVATION MATERIAL LEGEND

PAINT - 01 MTL-1 METAL - 01

PAINT - 02 BRK-2 BRICK - 01

- MANUFACTURERS.

 B. CLEAN FACADE USING GENTLEST MEANS POSSIBLE TO ACHIEVE SATISFACTORY RESULTS WITHOUT CHANGING THE SURFACE OF THE MASONRY, PAY SPECIAL ATTENTION TO AREAS OF EXCESSIVE SOILING, CONTRACTOR SHALL CONDUCT TEST PATCHES TO ENSURE THE BEST AND MOST ECONOMICAL MEANS OF CLEANING. ALL MASONRY AND TERRA COTTA CLEANING SHALL MEET THE SECRETARY OF INTERIOR STANDARDS FOR REHABILITATION AS WELL AS ALL APPLICABLE NATIONAL PRAK SERVICE TECHNICAL BRIEFS, SUBCONTRACTOR SHALL BE RESPONSIBLE FOR PROTECTING ALL SURROUNDING AREAS.
- C. CLEAN ALL STONE THAT IS TO REMAIN & LET WEATHER FOR TWO WEEKS BEFORE ANY REPLACEMENT OR PATCHING IS TO OCCUR - REPLACEMENT STONE & PATCHED AREAS TO MATCH EXIST 'CLEANED' COLOR
- D. RESTORATION CONTRACTOR SHALL INSPECT ALL EXISTING MASONRY, INCLUDING BOTH SIDES OF PARAPET FULL HEIGHT, FOR STRUCTURAL STABILITY PRIOR TO BID. REINSPECT AFFER INTIAL CLEANING OF MASONRY.
- REINSPECT AFTER INITIAL CLEANING OF MASONRY.

 E. REPLACE/RESET LOSSE MASONRY UNITS AND TUCKPOINT DAMAGED MORTAR JOINTS AS REQUIRED. JOINTS SHALL BE RINSED WITH CLEAN WATER REMOVING DUST AND DEBRIS. IF NECESSARY, RECOMMEND FURTHER REHABILITATION TO ENSURE STABLITY OF EXTERIOR WALL AND PARAPET CONSTRUCTION. SEE MASONRY RESTORATION SPECIFICATIONS FOR DETAILS ON APPROVED RESTORATION PROCEDURES, PRODUCTS, AND MANUFACTURERS. ALL MASONRY RESTORATION WORK SHALL MEET THE SECRETARY OF INTERIOR STANDARDS FOR REHABILITATION AS WELL AS ALL APPLICABLE NATIONAL PARK SERVICE TECHNICAL BRIFES.

 INSPECT GALL TERRAC COTTAL UNITS FOR DAMAGE SPALL HIGH, OR CRAZING.
- G. WHERE TERRA COTTA GLAZING HAS SPALLED AND THE CLAY SUBSTRATE IS IN GOOL CONDITION. COAT RAW CLAY WITH APPROVED BREATHABLE SEALER TO MATCH
- CONDITION, COAT RAW CLAY WITH APPROVED BREATHABLE SEALER TO MATCH
 COLOR OF EXISTING GLAZING.

 H. WHERE TERRA COTTA UNITS HAVE SPALLED SIGNIFICANTLY, PATCH DAMAGED AREAS
 WITH APPROVED MASONRY REPAIR MORTAR AS REQUIRED BY DEPTH OF DAMAGED
- WITH AFFANCED WIRSDWINT INFERIOR WOUNDAY AS REQUIRED OF DEFETH OF DIMINISED AREA. COAT PATCHED AREA WITH APPROVED BREATHABLE SEALER TO MATCH COLOR OF EXISTING GLAZING.
 WHERE TERRA COTTA HAS DETERIORATED REYOND REPAIR. REMOVE AFFECTED.
- WHERE TERRA COTTA HAS DETERIORATED BEYOND REPAIR, REMOVE AFFECTED
 TERRA COTTA UNITS AND PROVIDE NEW TERRA COTTA UNITS TO MATCH EXISTING
 PROFILE, COLOR AND FINISH.

 SEE TERRA COTTA RESTORATION SPECIFICATIONS FOR APPROVED RESTORATION
 PROCEDURES, PRODUCTS, AND MANUFACTURERS. ALL TERRA COTTA RESTORATION
 WORK SHALL MEET THE SECRETARY OF INTERIOR STANDARDS FOR REHABILITATION
 AS WELL AS ALL APPLICABLE NATIONAL PRAIK SERVICE TECHNICAL BRIEFS.
- K. REMOVE ALL VINES FROM ENTIRE BUILDING FACADES.
- L. REMOVE EXISTING WINDOW AIR CONDITIONERS. PROVIDE WINDOW STOPS TO LIMIT OPENING TO LESS THAN 4".
- UPENING TO LESS THAN 4".

 MASONRYSTONE RESTORATION CONTRACTOR ("SUBCONTRACTOR") TO PROVIDE ALL LABOR, MATERIAL, EQUIPMENT, SUPERVISION, PERMITS, AND ANY COSTS OR EXPENSES NECESSARY TO COMPLETE THE WORK SUBCONTRACTOR JOB MOBILIZATION SHALL INCLUDE, BUT NOT BE LIMITED TO ANY NECESSARY WORK STATION AND JOB TRAILER, MAST CLIMBRO PLATFORMS, ARERIAL LIFTS, SWING STACES, BARRICADES AND WALK THROUGH SCAFFOLD AS NEEDED.
- N. BUILDING RESTORATION TO INCLUDE ALL TERMS, CONDITIONS, AND SPECIFICATIONS OF ORIGINAL CONTRACT AND ANY ADDITIONAL WORK NECESSARY TO MEET THE SECRETARY OF THE INTERIOR STANDARDS FOR THE REHABILITATION OF HISTORIC PROPERTIES. THIS INCLUDES ALL WORK NECESSARY OVER AND ABOUT THAT SPECIFIED IN THE ARCHITECTURAL DRAWNINGS AND OTHER CONSTRUCTION DOCUMENTS, INCLUDING ALL NOTES, REGARDLESS OF TIME AND MATERIAL RECESSARY TO EXECUTE THIS WORK, ANY AREAS INJUNCATE WITHIN DRAWNINGS ARE ONLY SUGGESTIVE IN NATURE. MASON TO MEET WITH ARCHITECT AND OWNER TO CONFIRM THE SCOPE OF WORK.
- O. SURFACES TO BE PRE-WET WITH CLEAN WATER. CLEANING SOLUTIONS TO NOT REMAIN ON SURFACES FOR MORE THAN 5 MINUTES FOLLOWED IMMEDIATELY BY LOW-PRESSURE FLOOD RINSE, UND IN MASONRY CLEANING SPECIFICATION.
 CLEANING IS TO BRING MASONRYSTONE UNIT AS CLOSE AS POSSIBLE TO ORIGINAL COLOR WITHOUT BURNING OR ABRASION.
- COLOR WITHOUT BURNING OR ABRASION.
 P. 100% OF MORTAR JOINTS TO BE VISUALLY INSPECTED. ALL MORTAR JOINTS
 DETERIORATED IN EXCESS OF 3/8 INCH BEYOND FACE OF MASONNY/STONE UNIT, OR
 FUIDENCING UNSOUNDNESS OR CRACKING WHETHER STRUCTURAL OR OTHERWISE
 SHALL BE REMOVED TO A DEPTH OF 1/2" MINIMUM, WRITTEN APPROVAL BY OWNER
 SHALL BE REQUIRED PRIOR TO COMMENCEMENT OF REPAIR BY SATISFACTORY
 SUBMISSION OF MOCK-UP OF PROPOSED MORTAR JOINT.
- Q. NEW MORTAR APPLIED TO ALL OPEN JOINTS SHALL BE OF NO GREATER STRENGTH THAN ORIGINAL MORTAR OR MASONRY UNITS. MORTAR COLOR, TEXTURE, CONSISTENCY AND JOINT PROFILE WILL MATCH EXISTING AS CLOSE AS POSSIBLE.
- R. APPLY NEW, TWO COMPONENT WILL WAILCH EASI MIKE AS LUCE AS PUSSIBLE.

 BY APPLY NEW, TWO COMPONENT WERTHANE SEALANT AT ALL JOINTS WHERE

 DISSIMILAR MATERIALS MEET, AND ALL SKYWARD FACING JOINTS. BACKER ROD TO BE

 INSTALLED IN OPEN JOINT PRIOR TO SEALANT APPLICATION.

 S. NO ACCELERATORS OR OTHER ADMINITURES SHALL BE USED WITHOUT PRIOR

 S. NO ACCELERATORS OR OTHER ADMINITURES SHALL BE USED WITHOUT PRIOR
- NO ACCELERATORS OR OTHER ADMIXTURES SHALL BE USED WITHOUT PRIOR WRITTEN OWNER APPROVAL. ENCLOSURES AND HEAT SUFFICIENT TO PROTECT MORTAR FROM FREEZING PRIOR TO SET SHALL BE THE SOLE RESPONSIBILITY OF SUBCONTRACTOR.
- SUBLUM MACTOR.

 ANY MASONRY/STONE UNIT SHALL BE REPLACED WITH OWNER APPROVED MATERIAL WHEREIN SPALLING OR OTHER DETERIORATION ELIMINATED MORE THAN 5% OF THE MASONRY/STONE UNIT (MEASURED BY BRICK OR STONE FACE AREA.)

KraemerDesignGroup

Consultar

TAPESTRY BY HILTON
2305 PARK AVENUE
BETROIT MI 48226
MHS GROUP
35 W LONGLAKE
BLOOMFIELD HILLS, MI
48304

PRELIMINARY NOT FOR CONSTRUCTION

Seal

Project / Owner

THIS DOCUMENT AND THE IDEAS AND DESIGNS INCORPORATED HEREIN, AS AN INSTRUMENT OF PROFESSIONAL SERVICE ARE THE PROPERTY OF KRAEMER DESIGN GROUP, LLC AND ARE NOT TO BE USED IN WHOLE OR IN PART FOR ANY REASON WITHOUT THE WRITTEN AUTHORIZATION OF KRAEMER DESIGN GROUP, LLC.

GCOPYRIGHT 2018 KRAEMER DESIGN GROUP, LLC

CD REVIEW 12-16-19

DD BRAND REVIEW 10-09-19
SD BRAND REVIEW 09-06-19
SD OWNER REVIEW 02-20-19
OWNER REVIEW 02-06-19

Revision Date

Date

Project Number 2018069


Sheet Title

EXTERIOR ELEVATION

Sheet Number

A202

0 2' 4' 8' 16 SCALE: 1/8" = 1'-0"



- 201 EXISTING WALL PAINT TO BE RESTORED WITH NEW TEXT "HOTEL ROYAL PALM".
 206 REMOVE GRAFFITI BRICK PAINT WITH GENTLEST MEANS POSSIBLE TO ACHIEVE
 SATISFACTORY RESULTS, PROVIDE MOCKUP. JE SATISFACTOR RESULTS ARE NOT
 ACHIEVEABLE, RE-PAINT BRICK WITH COLOR TO MATCH BRICK ABOVE.
- 213 RE-INSTALL HISTORIC SIGNAGE LIGHTING.

EXTERIOR ELEVATION MATERIAL LEGEND

PNT-1	PAINT - 01	MTL-1	METAL - 01
PNT-2	PAINT - 02	BRK-2	BRICK - 01
PNT-3	PAINT - 03	STNE-3	STONE - 01

RESTORATION GENERAL NOTES

- A. ALL ELEVATIONS SHALL UNDERGO COMPLETE BRICK, STONE, AND TERRA COTTA CLEANING FROM PARAPET TO GRADE. SEE MASONRY CLEANING SPECIFICATION SECTIONS FOR DETAILS ON APPROVED CLEANING PROCEDURES, PRODUCTS, AND MANUFACTURERS.
- MANUFACTURERS.

 B. CLEAN FACADE USING GENTLEST MEANS POSSIBLE TO ACHIEVE SATISFACTORY RESULTS WITHOUT CHANGING THE SUBFACE OF THE MASONRY, PAY SPECIAL ATTENTION TO AREAS OF EXCESSIVE SOILING. CONTRACTOR SHALL CONDUCT TEST PATCHES TO ENSURE THE BEST AND MOST ECONOMICAL MEANS OF CLEANING. ALL MASONRY AND TERRA COTTA CLEANING SHALL MET THE SECRETARY OF INTERIOR STANDARDS FOR REHABILITATION AS WELL AS ALL APPLICABLE NATIONAL PARK SERVICE TECHNICAL BRIEFS, SUBCONTRACTOR SHALL BE RESPONSIBLE FOR PROTECTION ALL SUBLEMBLES.
- C. CLEAN ALL STONE THAT IS TO REMAIN & LET WEATHER FOR TWO WEEKS BEFORE ANY REPLACEMENT OR PATCHING IS TO OCCUR - REPLACEMENT STONE & PATCHED AREAS TO MATCH EXIST 'CLEANED' COLOR
- D. RESTORATION CONTRACTOR SHALL INSPECT ALL EXISTING MASONRY, INCLUDING BOTH SIDES OF PARAPET FULL HEIGHT, FOR STRUCTURAL STABILITY PRIOR TO BID. REINSPECT AFTER INITIAL CLEANING OF MASONRY.
- REINSPECT AFTER INITIAL CLEANING OF MASONRY.

 REPLACE/RESET LOSE MASONRY UNITS AND TUCKPOINT DAMAGED MORTAR JOINTS AS REQUIRED. JOINTS SHALL BE RINSED WITH CLEAN WATER REMOVING DUST AND DEBRIS. IF NECESSARY, RECOMMEND FURTHER REHABILITATION TO ENSURE STABILITY OF EXTERIOR WALL AND PARAPET CONSTRUCTION. SEE MASONRY RESTORATION SPECIFICATIONS FOR DETAILS ON APPROVED RESTORATION PROCEDURES, PRODUCTS, AND MANUFACTURERS. ALL MASONRY RESTORATION WORK SHALL MEET THE SECRETARY OF INTERIOR STANDARDS FOR REHABILITATION AS WELL AS ALL APPLICABLE NATIONAL PARK SERVICE TECHNICAL BRIEFS.

 INSPECT ALL TERRA COTTAIN LINTS FOR DAMAGE SPAIL HIGO RE CRAZING.
- G. WHERE TERRA COTTA GLAZING HAS SPALLED AND THE CLAY SUBSTRATE IS IN GOO CONDITION. COAT RAW CLAY WITH APPROVED BREATHABLE SEALER TO MATCH
- COLOR OF EXISTING GLAZING.

 H. WHERE TERRA COTTA UNITS HAVE SPALLED SIGNIFICANTLY, PATCH DAMAGED AREAS WITH APPROVED MASONRY REPAIR MORTAR AS REQUIRED BY DEPTH OF DAMAGED AREA. COAT PATCHED AREA WITH APPROVED BREATHABLE SEALER TO MATCH
- UNITED THE TERRA COTTA HAS DETERIORATED BEYOND REPAIR, REMOVE AFFECTED TERRA COTTA UNITS AND PROVIDE NEW TERRA COTTA UNITS TO MATCH EXISTING PROFILE, COLOR AND FINISH.
- J. SEE TERRA COTTA RESTORATION SPECIFICATIONS FOR APPROVED RESTORATION PROCEDURES, PRODUCTS, AND MANUFACTURERS. ALL TERRA COTTA RESTORATION WORK SHALL MEET THE SECRETARY OF INTERIOR STANDARDS FOR REHABILITATION AS WELL AS ALL APPLICABLE NATIONAL PARK SERVICE TECHNICAL BRIEFS.
- REMOVE ALL VINES FROM ENTIRE BUILDING FACADES.

COLOR OF EXISTING GLAZING.

- REMOVE EXISTING WINDOW AIR CONDITIONERS. PROVIDE WINDOW STOPS TO LIMIT OPENING TO LESS THAN 4".
- UPENING TO LESS THAN 4".

 MASONRYSTONE RESTORATION CONTRACTOR ("SUBCONTRACTOR") TO PROVIDE ALL LABOR, MATERIAL, EQUIPMENT, SUPERVISION, PERMITS, AND ANY COSTS OR EXPENSES NECESSARY TO COMPLETE THE WORK SUBCONTRACTOR JOB MOBILIZATION SHALL INCLUDE, BUT NOT BE LIMITED TO ANY NECESSARY WORK STATION AND JOB TRAILER, MAST CLIMBRO PLATFORMS, ARERIAL LIFTS, SWING STACES, BARRICADES AND WALK THROUGH SCAFFOLD AS NEEDED.
- N. BUILDING RESTORATION TO INCLUDE ALL TERMS, CONDITIONS, AND SPECIFICATIONS OF ORIGINAL CONTRACT AND ANY ADDITIONAL WORK NECESSARY TO MEET THE SCERETARY OF THE INTERIOR STANDARDS FOR THE REHABILITATION OF HISTORIC PROPERTIES. THIS INCLUDES ALL WORK NECESSARY OVER AND ABOVE THAT SPECIFIED IN THE ARCHITECTURAL DRAWINGS AND OTHER CONSTRUCTION DOCUMENTS, INCLUDING ALL MORES, REGARDLESS OF TIME AND MATERIAL NECESSARY TO EXECUTE THIS WORK, ANY AREAS INDICATED WITHIN DRAWINGS ARE ONLY SUGGESTIVE IN NATURE. MASON TO MEET WITH ARCHITECT AND OWNER TO CONFIRM THE SCOPE OF WORK.
- O. SURFACES TO BE PRE-WET WITH CLEAN WATER. CLEANING SOLUTIONS TO NOT REMAIN ON SURFACES FOR MORE THAN 5 MINUTES FOLLOWED IMMEDIATELY BY LOW-PRESSURE FLOOD RINSE, UND IN MASONRY CLEANING SPECIFICATION. CLEANING IS TO BRING MASONRYSTONE UNIT AS CLOSE AS POSSIBLE TO ORIGINAL CLOOP. WITHOUT BURINDING OR ABRASION.
- COLOR WITHOUT BURNING OR ABRASION.
 P. 100% OF MORTAR JOINTS TO BE VISUALLY INSPECTED. ALL MORTAR JOINTS
 DETERIORATED IN EXCESS OF 3/8 INCH BEYOND FACE OF MASONNY/STONE UNIT, OR
 FUIDENCING UNSOUNDNESS OR CRACKING WHETHER STRUCTURAL OR OTHERWISE
 SHALL BE REMOVED TO A DEPTH OF 1/2" MINIMUM, WRITTEN APPROVAL BY OWNER
 SHALL BE REQUIRED PRIOR TO COMMENCEMENT OF REPAIR BY SATISFACTORY
 SUBMISSION OF MOCK-UP OF PROPOSED MORTAR JOINT.
- Q. NEW MORTAR APPLIED TO ALL OPEN JOINTS SHALL BE OF NO GREATER STRENGTH THAN ORIGINAL MORTAR OR MASONRY UNITS. MORTAR COLOR, TEXTURE, CONSISTENCY AND JOINT PROFILE WILL MATCH EXISTING AS CLOSE AS POSSIBLE.
- C. APPLY NEW, TWO COMPONENT URETHANE SEALANT AT ALL JOINTS WHERE DISSIMILAR MATERIALS MEET, AND ALL SKYWARD FACING JOINTS. BACKER ROD TO BE INSTALLED IN OPEN JOINT PRIOR TO SEALANT APPLICATION.
- S. NO ACCELERATORS OR OTHER ADMIXTURES SHALL BE USED WITHOUT PRIOR WRITTEN OWNER APPROVAL. ENCLOSURES AND HEAT SUFFICIENT TO PROTECT MORTAR FROM FREEZING PRIOR TO SET SHALL BE THE SOLE RESPONSIBILITY OF SUBCONTRACTOR.
- SUBCONTRACTION.

 1. ANY MASONRY/STONE UNIT SHALL BE REPLACED WITH OWNER APPROVED MATERIAL WHEREIN SPALLING OR OTHER DETERIORATION ELIMINATED MORE THAN 5% OF THE MASONRY/STONE UNIT (MEASURED BY BRICK OR STONE FACE AREA.)

KraemerDesign Group

Consultant

ROYAL PALM DETROIT

TAPESTRY BY HILTON
2305 PARK AVENUE
DETROIT MI 48226

MHS GROUP
35 W LONGLAKE
BLOOMFIELD HILLS, MI
48304



Seal

THIS DOCUMENT AND THE IDEAS AND DESIGNS INCORPORATED HERBIN, AS AN INSTRUMENT OF PROFESSIONAL SERVICE ARE THE PROPERTY OF KRAEMER DESIGN GROUP, LLC AND ARE NOT TO USED IN WHOLE OR IN PART FOR ANY REASON WITHOUT THE WRITTEN AUTHORIZATION OF KRAEMER DESIGN GROUP, LLC.

OCOPYRIGHT 2018 KRAEMER DESIGN GROUP, LLC

CD REVIEW 12-16-19

DD BRAND REVIEW 12-16-19

SD BRAND REVIEW 09-06-19

SD OWNER REVIEW 02-20-19

OWNER REVIEW 02-06-19

Revision Date


Date

Project Number 2018069
Sheet Title

EXTERIOR ELEVATION

Sheet Number

A203



- 200 REMOVE AND REPLACE CORRODED BRICK RELIEF ANGLE. SEE DETAIL X/SXXX.
 201 EXISTING WALL PAINT TO BE RESTORED WITH NEW TEXT "HOTEL ROYAL PALM"
- 202 INFILL SECURITY BARS AND SILL TO BE REMOVED. INSTALL NEW WINDOWS TO MATCH HISTORIC PROFILE, SEE A621.
- NOTION INSTRUMENATION. SEE MOZ.1.

 CAREFULLY DETACH EXISTING WETAL GUARDRAILS. CLEAN WITH GENTLEST
 MEANS POSSIBLE TO ACHIEVE SATISFACTORY RESULTS. INSPECT FOR DAMAGE
 AND REPAIRS AS FOURIED TO MAKE SECURE. RE-PAINT GUARD RAIL WITH
 COMPATABLE COLOR AND RE-INSTALL.
- 205 TUCKPOINT BRICK SPECIFICALLY NOTED TO BE REQUIRED AT THIS LOCATION. SEE GENERAL NOTES AND SPEC.
- 207 REPLACE EXISTING ALLEY BUILDING BUMPER GUARD.
- 209 REPLACE EXISTING FABRIC CANOPY AT HOTEL ENTRY. HOTEL SIGNAGE APPLIED AT FACE AND SIDES. SIDEWALK LIGHTING.
- 213 RE-INSTALL HISTORIC SIGNAGE LIGHTING.
- 214 HISTORIC LOCATION OF ENTRY AND BLADE SIGN. DELAYED SUBMITTAL FOR SIGNAGE PERMIT.

EXTERIOR ELEVATION MATERIAL LEGEND

Į	PNT-1	PAINT - 01	MTL-1	METAL - 01	
	PNT-2	PAINT - 02	BRK-2	BRICK - 01	
ſ	DNT.2	PAINT - 03	STME 2	STONE - 01	

RESTORATION GENERAL NOTES

- ALL ELEVATIONS SHALL UNDERGO COMPLETE BRICK, STONE, AND TERRA COTTA CLEANING FROM PARAPET TO GRADE. SEE MASONRY CLEANING SPECIFICATION SECTIONS FOR DETAILS ON APPROVED CLEANING PROCEDURES, PRODUCTS, AND MANUFACTURERS.
- B. CLEAN FACADE USING GENTLEST MEANS POSSIBLE TO ACHIEVE SATISFACTORY RESULTS WITHOUT CHANGING THE SURFACE OF THE MASONRY. PAY SPECIAL ATTENTION TO AREAS OF EXCESSIVE SOILING, CONTRACTOR SHALL CONDUCT TEST PATCHES TO ENSURE THE BEST AND MOST ECONOMICAL MEANS OF CLEANING. ALL MASONRY AND TERRA COTTA CLEANING SHALL MEET THE SECRETARY OF INTERIOR
 STANDARDS FOR REHABILITATION AS WELL AS ALL APPLICABLE NATIONAL PARK SERVICE TECHNICAL BRIEFS. SUBCONTRACTOR SHALL BE RESPONSIBLE FOR PROTECTING ALL SURROUNDING AREAS.
- CLEAN ALL STONE THAT IS TO REMAIN & LET WEATHER FOR TWO WEEKS BEFORE ANY REPLACEMENT OR PATCHING IS TO OCCUR - REPLACEMENT STONE & PATCHED AREAS TO MATCH EXIST 'CLEANED' COLOR
- TO MATCH EXIST 'CLEANED' COLOR
 RESTORATION CONTRACTOR SHALL INSPECT ALL EXISTING MASONRY, INCLUDING
 BOTH SIDES OF PARAPET FULL HEIGHT, FOR STRUCTURAL STABILITY PRIOR TO BID,
 REINSPECT AFTER INITIAL CLEANING OF MASONRY.
 REPLACE/RESET LOOSE MASONRY UNITS AND TUCKPOINT DAMAGED MORTAR JOINTS
 AS REQUIRED. JOINTS SHALL BE RINSED WITH CLEAN WATER REMOVING DUST AND
 DEBRIS. IF NECESSARY, RECOMMEND FURTHER REHABILITATION TO ENSURE
 STABILITY OF EXTERIOR WALL AND PARAPET CONSTRUCTION. SEE MASONRY
 RESTORATION SPECIFICATIONS FOR DETAILS ON PROPOVED RESTORATION
 PROCEDURES, PRODUCTS, AND MANUFACTURERS. ALL MASONRY RESTORATION
 PROCEDURES, PRODUCTS, AND MANUFACTURERS. ALL MASONRY RESTORATION
 WORK SHALL MEETTHE SEPERARY OF INTEREDRE STANDARDS FOR BEHABILITATION. WORK SHALL MEET THE SECRETARY OF INTERIOR STANDARDS FOR REHABILITATION AS WELL AS ALL APPLICABLE NATIONAL PARK SERVICE TECHNICAL BRIEFS.
- INSPECT ALL TERRA COTTA UNITS FOR DAMAGE, SPALLING OR CRAZING.
 WHERE TERRA COTTA GLAZING HAS SPALLED AND THE CLAY SUBSTRATE IS IN GOOD
- CONDITION, COAT RAW CLAY WITH APPROVED BREATHABLE SEALER TO MATCH COLOR OF EXISTING GLAZING.
- WHERE TERRA COTTA UNITS HAVE SPALLED SIGNIFICANTLY, PATCH DAMAGED AREAS WHERE LENRA COLTA UNITS HAVE SYALLED SIGNIFICANTIC, YALCH DAMAGED AREA
 WITH APPROVED MASONNY REPAIR MORTAR AS REQUIRED BY DEPTH OF DAMAGED
 AREA. COAT PATCHED AREA WITH APPROVED BREATHABLE SEALER TO MATCH
 COLOR OF EXISTING GLAZING.
 WHERE TERRA COTTA HAS DETERIORATED BEYOND REPAIR, REMOVE AFFECTED
- TERRA COTTA UNITS AND PROVIDE NEW TERRA COTTA UNITS TO MATCH EXISTING PROFILE, COLOR AND FINISH.
- SEE TERRA COTTA RESTORATION SPECIFICATIONS FOR APPROVED RESTORATION PROCEDURES, PRODUCTS, AND MANUFACTURERS. ALL TERRA COTTA RESTORATION WORK SHALL MEET THE SECRETARY OF INTERIOR STANDARDS FOR BEHABILITATION AS WELL AS ALL APPLICABLE NATIONAL PARK SERVICE TECHNICAL BRIEFS.
- REMOVE ALL VINES FROM ENTIRE BUILDING FACADES.
- REMOVE ALL VINES FROM ENTIRE BUILDING FACADES.
 REMOVE EXISTING WINDOW AIR CONDITIONERS, PROVIDE WINDOW STOPS TO LIMIT OPENING TO LESS THAN 4".

 MASONRY/STOME RESTORATION CONTRACTOR ("SUBCONTRACTOR") TO PROVIDE ALL LABOR, MATERIAL, EQUIPMENT, SUPERVISION, PERMITS, AND ANY COSTS OR EXPENSES NECESSARY TO COMPLETE THE WORK SUBCONTRACTOR IOB MOBILIZATION SHALL INCLUDE, BUT NOT BE LIMITED TO ANY NECESSARY WORK. STATION AND JOB TRAILER, MAST CLIMBING PLATFORMS, AERIAL LIFTS, SWING STAGES, BARRICADES AND WALK THROUGH SCAFFOLD AS NEEDED.
- STAGES, BARRICADES AND WALK THROUGH SCAFFOLD AS NEEDED.
 BUILDING RESTORATION TO INCLUDE ALL TERMS, CONDITIONS, AND SPECIFICATIONS
 OF ORIGINAL CONTRACT AND ANY ADDITIONAL WORK NECESSARY TO MEET THE
 SECRETARY OF THE INTERIOR STANDARDS FOR THE REHABILITATION OF HISTORIC
 PROPERTIES. THIS INCLUDES ALL WORK NECESSARY OVER AND ABOVE THAT SPECIFIED
 IN THE ARCHITECTURAL DRAWINGS AND OTHER CONSTRUCTION DOCUMENTS,
 INCLUDING ALL NOTES, REGARDLESS OF TIME AND MATERIAL RECESSARY TO
 EXECUTE THIS WORK. ANY AREAS INDICATED WITHIN DRAWINGS ARE ONLY
 SUGGESTIVE IN NATURE. MASON TO MEET WITH ARCHITECT AND OWNER TO
 CONFIRM THE SCOPE OF WORK.
- SURFACES TO BE PRE-WET WITH CLEAN WATER. CLEANING SOLUTIONS TO NOT O. SURFACES TO BE PRE-WET WITH CLEAN WATER. CLEANING SOLUTIONS TO NOT REMAIN ON SURFACES FOR MORE THAN S MINUTES FOLLOWED IMMEDIATELY BY LOW-PRESSURE FLOOD RINSE, UND IN MASONRY CLEANING SPECIFICATION. CLEANING STO BRING MASONRY/STORE UNIT AS CLOSE AS POSSIBLE TO ORIGINAL COLOR WITHOUT BURNING OR ABRASION.
 P. 100% OR MORTAR I IONITS TO BE VISUALLY INSPECTED, ALL MORTAR JOINTS DETERIORATED IN EXCESS OF 3/8 INICH BEYOND FACE OF MASONRY/STONE UNIT, OR DELIDER/TIME LINSCUMMENSES OF PRAY/WITHOUT SURFIT HE STORT HAD NOT THE MYSTER OF THE PROPERTY.
- EVIDENCING UNSOUNDNESS OR CRACKING WHETHER STRUCTURAL OR OTHERWISE SHALL BE REMOVED TO A DEPTH OF 1/2" MINIMUM. WRITTEN APPROVAL BY OWNER SHALL BE REQUIRED PRIOR TO COMMENCEMENT OF REPAIR BY SATISFACTORY SUBMISSION OF MOCK-UP OF PROPOSED MORTAR JOINT.
- NEW MORTAR APPLIED TO ALL OPEN JOINTS ALL BE OF NO GREATER STRENGTH THAN ORIGINAL MORTAR OPING. OR MASONRY UNITS. MORTAR COLOR, TEXTURE, CONSISTENCY AND JOINT PROFILE WILL MATCH EXISTING AS CLOSE AS POSSIBLE.
- APPLY NEW, TWO COMPONENT URETHANE SEALANT AT ALL JOINTS WHERE DISSIMILAR MATERIALS MEET, AND ALL SKYWARD FACING JOINTS. BACKER ROD TO BE INSTALLED IN OPEN JOINT PRIOR TO SEALANT APPLICATION.
- INSTALLED IN OPEN JOINT FANOR TO SEALANT APPLICATION.

 NO ACCELERATORS OR OTHER ADMITTURES SHALL BE USED WITHOUT PRIOR WRITTEN OWNER APPROVAL ENCLOSURES AND HEAT SUFFICIENT TO PROTECT MORTAR FROM REEZING PRIOR TO SET SHALL BE THE SOLE RESPONSIBILITY OF SUBCONTRACTOR.
- ANY MASONRY/STONE UNIT SHALL BE REPLACED WITH OWNER APPROVED MATERIA WHEREIN SPALLING OR OTHER DETERIORATION ELIMINATED MORE THAN 5% OF THE MASONRY/STONE UNIT (MEASURED BY BRICK OR STONE FACE AREA.)

KraemerDesign Group

ROYAL PALM DETROIT
TAPESTRY BY HILTON
2305 PARK AVENUE
DETROIT MI 48226 GROUP LONG LAKE FIELD HILLS, MI 48304 MHS 35 W L

Project / Owner



ENT AND THE IDEAS AND DESIGNS INCORPORATED PROPERTY OF KRAEMER DESIGN GROUP, LLC AND ARE NOT USED IN WHOLE OR IN PART FOR ANY REASON WITHOUT TH WRITTEN AUTHORIZATION OF KRAEMER PROPERTY.

12-16-19 CD REVIEW DD BRAND REVIEW 10-09-19 SD BRAND REVIEW 09-06-19 SD OWNER REVIEW 02-20-19

OWNER REVIEW 02-06-19 Revision Date

2018069

Date


Project Number


Sheet Title


EXTERIOR ELEVATION

A204

SCALE: 1/8" = 1'-0"







Kraemer Design Group

October 28, 2019

Ms. Jennifer Ross City of Detroit Historic District Commission 2 Woodward Avenue Suite 808 Detroit, Michigan 48226

RE: Royal Palm Hotel - HDC Submission

Dear Ms. Ross:

Kraemer Design Group (KDG) is writing to submit information to the Detroit Historic District Commission (HDC), on behalf of Midwest Lodging Group regarding the proposed rehabilitation of the Royal Palm Hotel (RPH) located at 2305 Park Avenue. The proposed exterior work at the RPH will include: masonry cleaning and restoration of the exterior; removal of the flowerboxes below each storefront bay window on the ground level; new flowerboxes replaced at each storefront bay window; new exterior doors; new canopies over both the Montcalm entrance and the Park Avenue entrance; new signage in keeping in character with the historic signage; cleaning and repair of the iron and metal railings and flagpoles; and new windows in a few, select locations; new roofing and new rooftop mechanical equipment; and new exterior lighting.

The Royal Palm Hotel was constructed in 1925 for local hotel magnate Lew Tuller. Built at a time when Detroit was experiencing explosive growth, the Royal Palm Hotel was part of a grandiose plan on the part of Tuller and other Detroit builders to duplicate the character and real estate market of New York City. Designed by Louis Kamper the Royal Palm Hotel contains thirteen floors and is faced primarily in orange brick on the two primary facades (east and south) and beige brick on the two secondary facades (west and north). The building exhibits the typical high-rise arrangement of a vast expanse of plain brick, punctuated by window openings and—on the Park and Montcalm facades—is relieved by decorative Italian Renaissance-inspired detailing. Limestone is used on the east and south facades on the lower two floors while stone detailing appears around the paired windows on third floor and on the upper two floors. Iron railings appear at the paired windows on the twelfth floor and at the fifth floor in the central bay. The center window on the third floor of the Park Avenue façade has a console-supported stone balconette with an iron railing. There is an elaborate cornice made of glazed terra cotta that runs from the Montcalm façade around to the Park Avenue façade and turns the corner onto the north façade, terminating after one bay on the north façade. The west façade lacks the cornice entirely although the orange brick wraps the corner onto the west façade and runs for one bay—the remainder of the west façade is faced in beige brick.

Originally, the building contained 15 hotel rooms on each floor although the layout has been altered on some floors since then. The Royal Palm Hotel has two primary facades along Park Avenue and Montcalm with the two secondary facades facing onto two parking lots, one to the north and one to the west. The building is currently vacant awaiting remodel, and both restaurant spaces on the ground floor are also vacant.

The following is a detailed description of the proposed work and its historic implications:

Masonry Restoration

The brick, terra cotta, and limestone masonry on the exterior of the building are all in good condition overall. The masonry will be cleaned and inspected for damage. All damaged, deteriorating, or spalling masonry units are to be removed and replaced with new material to match original units. Missing units are to be replaced to match the remaining adjacent materials and new brick will match the existing as closely as possible in size, color, texture, and compressive strength. Any salvaged brick will be reused where replacement is needed before new brick is used. The cleaning will be done according to the Secretary of Interior Standards, and NPS Technical Preservation Briefs 1, 2 &

1st Floor Storefront Flowerboxes



Kraemer Design Group

Currently there are no storefronts on the ground floor as they were replaced with bay windows during a previous renovation by prior owners. Each bay window currently has a large flowerbox under each window unit. These flowerboxes will be removed both to facilitate repair of the masonry façade beneath and to install new flowerboxes that will match the current flowerboxes. The bay windows will remain in place.

Exterior Doors

The double doors on the Park Avenue entrance are wood with glazed units with decorative stainless-steel push bars across each door. These doors are not historic and are in fair condition. Above the doors there is a large iron fanlight with metal radiating muntins. The doors from Park Avenue into the main lobby will be replaced within the existing frame with units that complement the historic character of the building without appearing falsely historic. The Town Pump Tavern entry and doors are not historic and thus the doors on Montcalm Street will be replaced with new wood units to complement historic character of the building without appearing falsely historic.

Exterior Awning/Canopy

There is a non-historic fabric awning over the Park Avenue entrance that will be removed and replaced with an arched glass and metal unit. The glass and metal canopy above the Montcalm Street entrance will be removed and replaced with a new canopy, made of contemporary materials, to complement the historic character of the building without drawing attention away from the existing historic material or appearing falsely historic. The new Montcalm canopy will be an arched metal frame with black metal panels overhead. Please see the attached drawings for additional details.

Exterior Signage

Historically, there was a blade sign on the east façade, right near the southeast corner of the building as well as a hanging blade sign located over the Montcalm entrance. Historically there was painted signage on the brick at the top of the building. Currently there is signage on the awning that covers the main Park Avenue entrance and applied letters at the Montcalm entrance.

This project proposes that signage may be added at: A blade sign on the east façade in the southeast corner of the building and a hanging blade sign on the south façade will both be re-introduced per historic precedence. The signs currently painted on the brick at the top of the building will be repainted to reflect the historic name for the hotel (Royal Palm Hotel). A plaque style sign will be installed on the Park Avenue façade adjacent to the main entry doors. Finally, above the door on Montcalm, there will be revised applied letters with the new Restaurant name.

Exterior Metal Railings and Flagpoles

This project will retain all the decorative metal railings and flagpoles. These railings and flagpoles will be retained, cleaned, and painted. Any broken or missing pieces shall be repaired or replaced to match the original as closely as possible.

Windows

Nearly all the windows in the building were replaced in 2005 and they are in good condition. The 2005-era windows on floors 2-13 are single-hung aluminum units. The windows that were replaced in 2005 will be cleaned and retained as is.

There are a few areas with older windows that are in poor condition: the windows on the north facade at the 1st floor are original and are in poor condition, there are two windows in the previous laundry room space that are boarded over and are in poor condition, and there are a whole column of windows on the west façade that are also in poor condition. Finally, there are currently steel frame windows in the penthouse in very poor condition.

The first-floor storefronts were removed by a previous owner and were replaced with recessed metal bay window units with faux copper hoods; these are in good condition.



Kraemer Design Group

The steel windows in the penthouse will be replaced with new aluminum units to complement the historic character of the building. The windows that were not replaced in 2005 will be removed and replaced with units that match the historic windows as closely as possible, these include: the column of windows on the west façade, the two windows in the laundry area (which will become the new fitness area), and the 1st floor north facade windows. Note that the replacement windows are all located on secondary facades (the west façade and the north façade).

On the west façade, two new columns of windows are proposed: one column to each side of the center column of existing windows. Please see the attached drawings for additional details.

Finally, several new punched openings are proposed on the west façade to accommodate louvered panels and fans for the venting the mechanical equipment. Please see the attached elevations for details.

The bay window units will be retained, inspected, cleaned, and repaired if necessary.

Exterior Roof Scope

The roofing system will be replaced with a new membrane roofing material. The penthouse will be retained and repaired as necessary and new mechanical units will be added to the roof; they will be placed around the penthouse. There will be no roof screen. Please see the attached sightline study regarding the visibility of these rooftop mechanical units.

Lighting

There are currently sconces on the building. These will be replaced with new up/down sconces. Historically, the building had gooseneck light fixtures that shone down on the painted signs at the top of the building. It is proposed that these lights will be reintroduced with new gooseneck fixtures—they will be added above the painted signage on the north façade, the west façade and on the south penthouse. New lighting will be added underneath the canopies as well. Please see the attached historic photograph.

The items listed above provide a synopsis of the proposed scope of work for the rehabilitation of the Royal Palm Hotel. Further detail is provided in the attached drawings, photos, and documentation. Please contact Brian Rebain at Kraemer Design Group if you have any further questions.


Sincerely,


Kraemer Design Group

Bi Peki


Brian Rebain Principal














VIEW S.1 from Columbia W & Park Ave




VIEW S.1 from Columbia W & Park Ave










VIEW S.2 from W Elizabeth St & Park Ave








VIEW S.3 from W Fisher Dr & Park Ave



VIEW S.3 from W Fisher Service Dr & Park Ave






VIEW S.4 from W Fisher Dr & Park Ave







VIEW S.4 from W Fisher Service Dr & Park Ave



















VIEW E.1 from Clifford St & W Montcalm













VIEW E.2 from Cass Ave & W Montcalm











VIEW E.3 from Woodward Ave & W Montcalm





GENERAL NOTES

- A WHERE SLAB ON GRADE REMOVAL IS REQUIRED FOR UTILITY PLACEMENT REFER TO

- RATING OR PARTITION OR FLOOR. SEE SPECIFICATIONS.

 D FIRE RATED PARTITIONS SHALL BE CONTINUOUS FROM FLOOR TO STRUCTURE ABOVE AND SHALL BE FIRE STOPPED TIGHTLY TO STRUCTURE PER CODE (U.L. SYSTEM).

 E WHERE NEW CYPSUM BOARD PARTITIONS ARE A CONTINUATION OF AN EXISTING PARTITION OR COLUMN ENCASEMENT, THE FACE OF THE NEW GYPSUM BOARD SHALL BE ALIGNED WITH THE FACE OF THE ENE FOR YEARY OFFENDED SHALL BE ALIGNED WITH THE FACE OF THE EXISTING SURFACE. WHERE A NEW GYPSUM BOARD PARTITION IS SHOWN INTERSECTING A COLUMN ENCASEMENT THE CENTERLINE OF THE WALL SHALL BE CENTERED ON THE COLUMN ENCASEMENT.
- F WHERE NEW OR INFILL PARTITION ABUTS EXISTING PARTITION, FACE OF PARTITIONS SHALL ALIGN, UNLESS NOTED OTHERWISE.
- G PARTITIONS WITH EXISTING FRAMING MAY REQUIRE REWORK TO ACCOMODATE NEW OPENINGS, ETC.
- H WHERE NEW FINISHES ARE SPECIFIED ON THE FINISH PLAN REMOVE ALL EXISTING FINISHES PATCH AND REPAIR WALLS AND FLOOR PREPARE THEM TO ACCEPT NEW SCHEDULED FINISH PER MANUAL SAND FLOOR PREPARE THEM TO ACCEPT NEW SCHED
- I LOCATE DOOR FRAMES 6" FROM INSIDE CORNER TO DOOR OPENING, UNLESS NOTED
- J ALL INTERIOR GLAZING INCL DOORS, SIDELITES, & BORROWED LITES SHALL BE CLEAR

- J ALL INTERIOR GLAZING INCL DOORS, SIDELITES, & BORROWED LITES SHALL BE CLEAR LAMINATED SAFETY GLASS OR CLEAR TEMPERED SAFETY GLAZING. UNILESS NOTED OTHERWISE.

 K CONTRACTOR SHALL PROVIDE AND INSTALL CORNER GUARDS (CG) AS IDENTIFIED ON PLANS. CG SHALL BE FULL HEIGHT FROM TOP OF BASE TO CEILING. TYP. EXCEPT AT VWC -INSTALL FROM TOP OF VWC TO CLE.

 L SEMI-RECESSED IRE EXTINGUISHER (FE)- REFER TO SHEET ASOL FOR TYPICAL DETAILS. FINAL LOCATION OF FIRE STYTINGUISHER (FE)- REFER TO SHEET ASOL FOR TYPICAL DETAILS. FINAL LOCATION OF FIRE STYTINGUISHERS SHALL BE REVIEWED IN FIELD WITH BUILDING OFFICIAL PRIOR TO INSTALLATION ROUGH-IN.

 M RECESSED ITEMS (GREATER THAN 16 SQ. IN.) IN RATED AND/OR SMOKE WALLS, INCLUDING ELEC PANELS, ELEC DUCTS, MED GAS VALVE BOXES, FIRE EXT CABINETS, ETC. SHALL BE BACKED WITH 5/8" TYPE 'X' GYPSUM BOARD TO MAINTAIM RATING FIRE WALL.
- N TELEPHONE AND ELECTRICAL PANEL BOARDS: PROVIDE AND INSTALL 4'X 8'X 3/4"
 THICK, PLYWOOD, FIRE RETARDANT TREATED.

 O REPAIR ALL EXISTING EXPOSED PLASTER OR THAT REQUIRED FOR FIRE RATING AS
 NOTED ON ASO1.

CONSTRUCTION KEYNOTES (###)

- 100 EXIST FLOOR OPENING TO BE INFILLED. FIELD VERIFY DIMENSIONS AND LOCATIONS- TYP. ALL STEEL DECKING AND SECTIONS TO HAVE FULL COVERAGE OF SPRAY-ON FIREPROOFING PER SPECIFICATIONS FOR A MINIMUM 2-HR FIRE-RESISTANCE RATED FLOOR ASSEMBLY, REFER TO STRUCTURAL.
- 106 EXISTING STAIR TO REMAIN AND BE RESTORED. SEE STAIR FINISH SCHEDULE

KraemerDesign Group

ROYAL PALM DETROIT
TAPESTRY BY HILTON
2306 PARK AVENUE
DETROIT MI 48226 MHS GROUP 35 W LONG LAKE BLOOMFIELD HILLS, MI 48304 Project / Owner

> PRELIMINARY (NOT FOR) CONSTRUCTION

DD BRAND REVIEW 10-09-19 SD BRAND REVIEW 09-06-19
 SD OWNER REVIEW
 02-20-19

 OWNER REVIEW
 02-06-19

Date Revision


Date

Project Number 2018069

Sheet Title

1ST FLOOR PLAN

A101



FIRST FLOOR PLAN

SCALE: 1/8" = 1'-0"

STAIR-E BASE

SCALE: 1/8" = 1'-0"







