

ESTIMATE Report ID: **223542** Job ID: 5021 tireman 7/24/2022

Lakeside Painting And Plaster Repair

C Williamson - Estimator

Cert #: United States License #: Mi

lakesideppr@gmail.com WWW.LAKESIDEPAINT.COM

Property

5021 Tireman St, Detroit, MI 48204

FRONT OF BUILDING

Description	QTY	иом	PPU	Total
1 Small plaster crack repair - up to 1ft	7	EA		
2 Plaster crack repair - up to 5ft	1	EA		
3 plaster crack - up to 2ft	4	EA		
4 plaster crack - up to 3ft	3	EA		
5 stucco patch up to 5 SF	1	EA		
6 skim stucco	78	EA		
7 Apply primer to prepped walls	112	SF		
		Area		
		Sub		
		Estimat		
	Es	timate ⁻		

Signature: Date:



This information is an itemized estimate for repair to the property located at the above captioned address. This estimate has been prepared with the intention of restoring this property to its' "pre-damaged" condition. The scope of repair, as outlined in this estimate, has been formulated based upon non-destructive observation only. Therefore, only the items specifically mentioned here have been included in this estimate for repair.

It is our intention that this estimate be as thorough and accurate as possible. However, upon demolition of the affected areas, we reserve the right to make a re-evaluation of the damage. Should any hidden and/or additional damage be discovered or any other additional work or repair become necessary, for any reason, an addendum and/or modification to this document will be added to this estimate.

A deposit of 50% of the balance is required on the first day of job start.