

11687 Greenfield Rd Suite #2, Detroit, MI 48227

Phone: 313-757-1350

Fax: 313-528-3033

Email: shikher@tsaconsultantsinc.com

Date: 10/30/2020

To: TSS Consultants

Subject: Historic Windows Repair estimate

Repair items:

- Remove the window sashes and the casings
- Repair or replace the damaged or broken ropes and balances
- Repair the interior jambs, casing and stops. Remove existing Lead-based paint and repaint
- Take the windows sashes offsite for repair and Lead-based paint stripping. Repaint window sashes.
- Re-glazed the exterior window to make sure there's no air filtration
- Re-install windows sashes with functional ropes and balances
- Remove and reinstall storm windows

\$975 for each window repaired – 23 windows -- \$22,425 Additional site work (storm windows, ropes and balances, jambs, casing and stops) -- \$6775

Total: 29,200

Thank you

Shikher Srivastava (Vice – President)