

Neighborhood Cluster Planning Sector 8

Neighborhood/Commercial Building Conditions by Block Face

- Stable Conditions
- Beginning Signs of Decline
- Advanced Signs of Decline
- Major Signs of Deterioration

Figure 16

CRS
Community Reinvestment Strategy
Detroit

N

0 0.5 1
Miles

Michigan Metropolitan Information Center 1997