

B-4: Photos




Side A



Side B



Side C



Side D



Garage



Painted Wood Shake & Deteriorated Sashes



Deteriorated Roof Rake & Soffit



Cracks on Side D of Porch



Masonry Step Crack (Side D of Porch)



Deteriorated Concrete Porch Floor



Deteriorated Exterior Window Components



Deteriorated Exterior Window Casing on Fixed Window



Most Windows are covered with Storm Sashes



Deteriorated Exterior Door Jamb




Cellar Windows Covered with Storm Sashes



Little Garden (Side C)



Foyer



Child Licks Glass on Door (Foyer)



Child Licks Window Sill (Living Room A Wall)



Child Licks Window Sill (Living Room C Wall)